

Mazda MX-5


RF 1.5 132 CUIR - LED - BOSE - GPS - CAMERA

05/2019
68 210
Benzine
1496
132 / 97 kw
145 (WLTP) / 143
(NEDC)
EURO 6
Manual 6
Front wheel drive
Grey
Gray Leather
2
2
2



- Alloy Wheels 16
- Bluetooth
- Cruise Control
- GPS
- KeyLess
- LED
- Light sensor
- PDC Rear
- Radio MEDIA
- Sport Seats
- Automatic Air Conditioning
- Central Locking
- Electric Mirror
- Heated Seats
- Leather Steering Wheel
- LED daytime running lights
- Multifunction Steering Wheel
- Power Windows
- Rear View Camera









Facture	Page	Client	TVA	Date		
092409090169	1 / 2	110677		26/09/2024		
JOB : 195018		DATE : 25/09/2024				
Voiture : 113263		MAZDA MX-5 RF 1.5 SKY-G 6MT 131 SKYCRUISE				
Chassis : JM2ND6EA600408976		Plaque : 1APF635	1 ^{ère} immatriculation : 03/05/2019	Badge :		
Km : 66.577		Date Km : 26/09/2024				
Référence	Description	Quantité	Prix	Total	Tva	Orig.
1	Main d'oeuvre Mazda	1,85	75,00	133,75	401	5
995641400CU14-20-1.5	Equivalence à Mazda 995641400	1,00	1,44	1,44	401	5
SUPRAW20 (208L)	SUPRAW20 (208L) reserve	4,30	19,83	85,27	401	5
HUILEFREINDOT5.1	Huile de frein Champion Dot 5.1 (1 litre)	0,50	8,11	4,06	401	1
PEO11430289A	Filtere à huile	1,00	15,11	15,11	401	1
PEE1133A09A	Filtere à air	1,00	32,89	32,89	401	1
NZY1264RZB	Savon lave-glace concentré 0.5	1,00	2,75	2,75	401	1
	SOUS JEU PATIN D'ETRIER AR	1,00	121,28	121,28	401	1
	Sous-total			386,56		
D-PET	Petites fournitures	1,00	1,86	1,86	401	5
D-ENVIRON	Contribution environnement	1,00	3,94	3,94	401	5
	Sous-total			5,80		
My Mazda 6 eme service						
Vidange d'huile						
Remplacement du filtre à huile						
Remplacement du joint de bouchon de vidange						
Remplacement du filtre à pollen						
Remplacement du liquide de frein						
Purge des 4 freins						
Purge du niveau d'antigel moteur et appoint						